Christopher, Anne

From:

Horwitz, Benjamin

Sent:

Monday, August 04, 2014 12:29 PM

To:

Christopher, Anne

Subject:

FW: Soldotna Y Chevron Documentation

----Original Message-----From: Horwitz, Benjamin

Sent: Monday, August 04, 2014 12:27 PM To: 'soldotnaychevron@alaska.net'

Subject: RE: Soldotna Y Chevron Documentation

Mark.

In addition, we are still missing leak reports for all 4 tanks for the months of July 2013, November 2013, January 2014, and February 2014. Also, as I mentioned in my previous email, tank 4 was not included on the slips that you sent for September and October 2013. Please send another slip from September and October 2013 that include tank 4 and any release detection records that you have for July 2013, November 2013, January 2014, and February 2014.

Thanks.

Ben

----Original Message-----From: Horwitz, Benjamin

Sent: Monday, August 04, 2014 11:39 AM

To: 'soldotnaychevron@alaska.net'

Subject: RE: Soldotna Y Chevron Documentation

Hi Mark,

I have been reviewing the release detection records you submitted during your inspection and the email you sent afterwards. It appears tank 4 had a failing leak test in August 2013, then was not listed again on the leak test reports until December 2013 (you provided slips for tanks 1-3 for September and October 2013, but tank 4 was not included; the November 2013 slip was missing for all 4 tanks). Can you provide any info on your response to the failing test and how long the tank was not receiving passing leak tests? The only records we have so far on tank 4 is that it failed in August 13, passed in December 13, and passed March-June 2014.

Thank you,

Ben

----Original Message----

From: soldotnaychevron@alaska.net [mailto:soldotnaychevron@alaska.net]

Sent: Wednesday, June 25, 2014 4:24 PM

To: Horwitz, Benjamin

Subject: Soldotna Y Chevron Documentation

Ben,

I found some of the folders I thought had been thrown out.

Attached is the autoleak reports for the last year.

Also attached is the tankology invoice that states the leak dector was installed on the unleaded pump and my line tightness testing and leak dector testing was completed and past.

The autoleak reports were very faint and didn't scan very well. I can mail you them if you need to verify

Thanks
Mark Rozak
Soldotna Y Chevron
907-252-2335 leave message if I don't answer